

124. Metal Spray Deposits on the First-Stage Turbine Blades

Honeywell Report, Figure 124